



- ② 2UF NONEXISTENT WITH MOTOROLA M15024 OUTPUT DEVICES
- ③ 100PF REPLACED WITH 330 PF WITH MOTOROLA M15024 OUTPUTS
- ④ 82PF WAS 220 PF ON OLDER MODULES