



Xantrex SW Parallel Cable Pin Out



MASTER	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
SLAVE	22	23	x	20	19	18	17	16	15	x	x	x	x	x	9	8	7	6	5	4	3	x	x	x	x



SLAVE	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
MASTER	x	x	21	20	19	18	17	16	15	x	x	x	x	x	9	8	7	6	5	4	x	1	2	x	x

Note: On SLAVE DB25 Male Jumper Pin 14 to 21

